7. MGB Mark II.

The introduction of the Mark II MGB has caused some confusion as to parts interpretation. The Mark II incorporates many Running Changes to both body and mechanical components which have occurred from given change points of Engine or Car Numbers and are identifiable as such in the parts list rather than as Mark II, a term which does not appear in the UK Parts List. It is essential, therefore, to have the full Engine Number, Car Number, Body Number with prefixes and on Late MGB the Commission Number located on the bonnet lock platform when ordering or interpreting parts.

So that you may be aware of some of the main changes to the MGB Series, we have detailed the more important below:-

Engine Unit	Commencing Engine Prefix
3 Main Bearing 1st Of Series	18GUH
3 " " Closed Circuit Breathing	18GAUH
5 " " " " "	18GBUH
5 " " " " " with Modified Cyl. Head, Water Pump Flywheel and Alternator.	18GDUH

Gearbox Unit

Part	Synchro	without Overdrive	18GUH, 18GAUH, 18GBUH
"	"	with "	18GRUH, 18GARUH, 18GBRUH
Full	"	without "	18GDUEH
"	"	with "	18GDRWEH

Rear Axle

Banjo Type - Prefix not known - mainly prior 1968 - identifiable by one piece pressed axle case and welded rear cover.

Tubed Type - Prefix not known - mainly from Jan., 1968 - identifia by fabricated axle case and detachable rear cover.

Electrical

Alternator	18GD
Starter - Pre-Engagement Type	18GD

Body

Numerous changes to panels and hardware requiring Car Number, i.e. YGHN3/12345 and Commission No. i.e. G23N/1234G and Body No. i.e. GBD1234.

The MGB Series commenced with Car Number Prefix YGHN3 (The Y indicates Australia) and the GD Engine commenced with the next series YGHN4

Following this the YGHN5 Series was released in approximately August of this year, this model also bearing the Mark II tag.

Parts Lists covering many of these late changes are not available for general distribution as yet, meanwhile a copy is on hand at Lapco where, we trust, we can be of assistance in supplying any information or parts required.

* * * * * * *

Model M.G.B. / BODY Parts List No. PUB1030 P.A. No. 71 Date MARCH, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
RG - 2		WINDSCREEN ASSEMBLY		AHH9825	1	YHN9/1691	Addition at Change Point.
		Pillar Assembly - Windscreen - RH		AHH9222	1	YHN10/569	
		- LH		AHH9223	1		
		Top Rail Assembly		AHH9837	1		
		Bracket - Hood Fastener		AHA8483	2		
		Rivet - Bracket - Hood Fastener to Rail		AHH7138	8		
		Anchor Bracket - Sun Visor		AHH9838	2		
		Rivet - Anchor Bracket to Rail		AHH7138	4		
		Washer - Plain		PWZ102	4		
		Bracket - Mounting - Interior Mirror		BHA963	1		
		Rivet - Mounting Bracket to Rail		AHH7138	4		
		Bottom Rail Assembly - Windscreen		AHH9225	1		
		Bracket - Bottom - Centre Rod - Windscreen		AHH9459	1		
		Rivet - Bracket to Bottom Rail		AHH7138	2		
		Glass - Windscreen - Laminated - High Impact		AHH8227A	1		
		Reinforcement - Bottom Corner - Windscreen - RH		AHH6394	1		
		- LH		AHH6395	1		
		Seal - Windscreen to Body		AHH7136	1		
		- Windscreen to Pillar - RH		27H4300	1		
		- LH		27H4300	1		
		Retainer - Seal - Pillar		AHH6409	2		
		Stud - Dot - No. 550		BHA4645	4		
		Rivet - Pop - Dot Fasteners to Pillar		DMP3040	4		
		SUN VISOR ASSEMBLY		BHH649	1		
		Nut - Lock - Visor to Pivot Bracket - Windscreen		LNZ203	2		
		Washer - Spherical		AHH8799	2		
RN3 - 1		Eyelet - Head Restraint		CZA4500	2		
		Washer - Finisher		CZA4263	2		
		Head Restraint Assembly - Complete		HYB4875	2		
		Head Restraint Assembly		CZA4346	2		
		Pad - Head Restraint		CZA4358	2		
		Cover Assembly		HYB4866	2		
		Screw - Plate to Restraint		RTZ806	4		
RO - 4	55	Knob - Fresh Air Vent		BHH612	1		

P.D 15

PARTS AMENDMENT ADVICE

Model	M.G.B. - MECHANICAL	PUB	1028	PA No.	76	Page	2	Date	AUG 1972

Page No.	Description	Item Ill. no.	NEW Part Number	Qty.	Change Point	Remarks
AB-15	Pump - Water	2A	GWP117	1		
	Bearing Assembly	5A	12A1389	1		
	Hub	9A	12H3362	1		
	Seal	10A	13H6187	1		
	Pulley - Fan and Water Pump	11A	12H3696	1		
AB-16	Washer	30A	PWZ204	4		
	Screw	32A	HZS415	4		
	Spacer - Fan	37	12H3910	1		
	Bolt - Fan to Water Pump	38	HBZ413	4		
AB-19	Manifold - Inlet	3B	8G774	1		
	- Exhaust	26A	12H3911	1		
	Nut - For Stud	33A	12A1975	6		
AC-2	Bracket - Engine Moubting - RH	40A	AHH7890	1		
	- LH	40B	BHH640	1		
AC-3	Cable Assembly - Choke Control	19A	BWH651	1		
	Washer - Plain - Rin to Throttle Lever	43	PWZ103	1		
AC-4	Bracket - Choke Cable		12H3916	1		
	Pin - Choke Cable - Inner to Relay Shaft Bracket		AHA6367	1		
	Screw		53K3503	1		
	Lever Assembly - Throttle		BHH632	1		
	Lever - Pick-Up		AUE587	1		
			AUE586	1		
	Lever Assembly - Choke		BHH636	1		
	Bracket - Trunnion - Choke and Throttle Cables		BHH558	1		
	Screw		HZS505	1		
	Washer - Spring		LWZ205	1	YHN9 - 1774	
	Screw		HZS404	1		
	Washer - Spring		LWZ204	1		
	Nut		FNZ504	1		
	Washer - Plain		PWZ204	1		
	Screw - Choke Cable to Trunnion Bracket		ACA5453	1		
D-2	Micro Petrol Filler	37	BHA4952	1		
D-3	Clip - Front Main Feed Pipe to Valance - LH		PCR507	2		
	Screw - Clip to Bracket		PMZ308	2		
	Washer - Spring - Clip to Valance Bracket		LWZ203	2		
	- Plain - Clip to Valance Bracket		PWZ203	2		
	Hose - Flexible - Filter to Front Carburettor		BHH641	1		
	Pipe - Petrol - Main Feed to Filter - Bent		BHH135	1		
	Hose - Flexible - Main Feed to Filter		BRT2804	1		
	Clip - Flexible Hose Ends to Filter and Carburettor		ACH5854A	4		
	Clip - Front Flexible Hose to Valance Bracket		PCR1007	1		
	Screw - Clip to Valance Bracket		PMZ308	1		
	Washer - Spring - Clip to Valance Bracket		LWZ203	1		
	- Plain		PWZ103	1		
	Pipe - Overflow - Front Carburettor		BHH669	1		
	- Rear Carburettor		BHH670	1		
	Pipe - Flexible - Carburettor to Carburettor		BRT2409	1		

NOTE This PARTS AMENDMENTS ADVICE is issued to enable your Parts Lists to be maintained in an updated condition at all times. Once these amendments have been entered this advice sheet can be filed in the front of the Parts List Binder.

PARTS AMENDMENT ADVICE

Model M.G.B. - MECHANICAL	PUB 1028	PA No. 76	Page 3	Date AUG 1972

Page No.	Description	Item Ill. no.	NEW Part Number	Qty.	Change Point	Remarks
D - 4	Rod - Control	1	12H2612	1		
	Joint - Ball	2	AHB9898	2		
	Nut	3	FNZ103	2		
	Piece - Distance	50	1B2925	1		
D - 8	Shield - Heat	1A	12H3948	1		
	Washer	1B	2K6810	1		
	Cleaner - Air - Front	6A	BHH546	1		
	- Rear	7A	BHH547	1		
	Choke Cable Abutment Assembly	22A	BHH564	1	YHN9 - 1774	
	Washer - Plain	23	PWZ103	1		
	Spring - Choke Return	24	AEC2075	1		
	Washer - Adaptor - Manifold - Anti-Run on Valve	25	51K3811	1		
	Plug - Adaptor - Manifold - Anti Run on Valve	26	AHH8414	1		
D - 9	Carburettor Assembly - Front	1C	CUD9115	1		
	- Rear	1D	CUD9116	1		
	Gasket - Carburettor to Inlet Manifold	12	AEC2083	6		
	Nut	13	NNZ505	4		
	Washer - Plain	14	PWZ105	2		

NOTE This PARTS AMENDMENTS ADVICE is issued to enable your Parts Lists to be maintained in an updated condition at all times. Once these amendments have been entered this advice sheet can be filed in the front of the Parts List Binder.

PARTS AMENDMENT ADVICE

Model M.G.B. MECHANICAL	PUB 1028	PA No. 76	Page 4	Date AUG 1972

Page No.	Description	Item Ill. no.	NEW Part Number	Qty.	Change Point	Remarks
D9 - A	CARBURETTOR - TYPE - S.U. H1F HORIZONTAL - INTERNAL FLOAT CHAMBER					Complete Page Added
	CARBURETTOR - FRONT	1*	CUD9115	1		
	- REAR	2*	CUD9116	1		
	Body - Front	3*	CUD2613	1		
	- Rear	4*	CUD2603	1		
	Pin - Piston Lift	5*	AUC2605	1		
	Spring - Pin	6*	AUC1151	1		
	Circlip	7*	AUC1250	1		
	CHAMBER AND PISTON ASSEMBLY	8*	CUD2736	1		
	Screw - Needle Locking	9*	AUD3308	1		
	Cap and Damper	10*	AUC8114	1		
	Washer - Fibre	11*	AUC4900	1		
	Spring - Piston - Red	12*	AUC4387	1		
	Screw - Chamber to Body	13*	AUC2175	3		
	Jet - Front Carburettor	14*	CUD2787	1		
	Rear Carburettor	15*	CUD2784	1		
	Bearing - Jet	16*	AUD3567	1		
	Washer - Sealing	17*	AUD3566	1		
	Screw - Bearing	18*	AUD3569	1		
	NEEDLE - JET (AAU)	19*	CUD1018	1		
	Spring - Needle	20*	AUD3306	1		
	Guide - Needle	21*	AUD3775	1		
	NEEDLE AND SEAT	22*	CUD2795	1		
	Float - Carburettor - Front	23*	AUD3571	1		
	- Rear	24*	AUD3570	1		
	Spindle - Float	25*	CUD2082	1		
	Bi-Metal	26*	CUD2399	1		
	Screw - Bi-Metal	27*	AUD3584	1		
	Spring - Coil	28*	AUD3583	1		
	Screw - Adjusting - Bi-Metal and Jet	29*	AUD3585	1		
	Ring - Sealing	30*	AUD3586	1		
	Cover - Float Chamber	31*	AUD4207	1		
	Ring - Sealing	32*	AUD3588	1		
	Washer - Spring	33*	LWZ303	4		
	Screw - Cover to Body	34*	AUD3590	4		
	Spindle - Throttle	35*	AUD3575	1		
	Disc - Throttle	36*	AUD4233	1		
	Screw - Disc	37*	AUC1358	2		
	Seal - Spindle	38*	AUD3577	2		

NOTE This PARTS AMENDMENTS ADVICE is issued to enable your Parts Lists to be maintained in an updated condition at all times. Once these amendments have been entered this advice sheet can be filed in the front of the Parts List Binder.

PARTS AMENDMENT ADVICE

Model M.G.B. - MECHANICAL	PUB 1028	PA No. 76	Page 5	Date AUG 1972

Page No.	Description	Item Ill. no.	NEW Part Number	Qty.	Change Point	Remarks
	CARBURETTOR - Continued					Complete Page Added.
D9 - B	Spindle - Starter Valve	39*	CUD2790	1		
	Seal - Spindle	40*	AUD3577	1		
	Body - Starter Valve	41*	AUD4212	1		
	Ring - 'O'	42*	AUD3602	1		
	Seal - Valve	43*	AUD3577	1		
	Plate - Valve Clamping - Front Carburettor	44*	AUD3604	1		
	Gasket - Plate	45*	AUD3605	1		
	Screw	46*	AUD3606	2		
	Lever - Cam - Front Carburettor	47*	AUD4285	1		
	- Rear Carburettor	48*	AUD4185	1		
	Spring - Lever Return	49*	AUD3609	1		
	Washer - Tab	50*	AUD3323	1		
	Nut	51*	AUC1424	1		

NOTE This PARTS AMENDMENTS ADVICE is issued to enable your Parts Lists to be maintained in an updated condition at all times. Once these amendments have been entered this advice sheet can be filed in the front of the Parts List Binder.

PARTS AMENDMENT ADVICE

Model	M.B.B. - MECHANICAL	PUB	1028	PA No.	76	Page	6	Date	AUG 1972

Page No.	Description	Item Ill. no.	NEW Part Number	Qty.	Change Point	Remarks
E - 2	Cover Assembly - Clutch	9A	13H6350	1		
	Plate - Clutch	10A	13H6351	1		
	Bearing Assembly	13A	13H5980	1		
	Retainer - Bearing	14A	75020	2		
F - 7	Bracket - Wiring Clip - Complete - Top RH Bolt on Front Gearbox Case	30	22B512	1		
	Bracket - Wiring Clip - Complete - Top Starter Motor Bolt	31*	22H1303	1		
	Clip - Bracket - Top RH - Rear of Gearbox	32	ACH579	1		
F - 21	Gasket - Remote Control to Gearbox Extension		22B372	1		
	Setscrew - Long		HCZ518	4		
	Short		ZCS508	2		
	Washer - Spring		LWZ305	6		
	Gasket		22B371	1		
	Washer - Spring		LWZ305	8		
F - 22	Wheel - Reverse		22H309	1		
	Bush		22H310	1		
	Shaft - 3rd Motion		22B424	1		
F - 24	Plug	▲	22B612	1		
	Plunger - Detent - Reverse		22B614	1	YHN9 - 1774	
F - 25	Lever - Clutch Withdrawal		22H1057	1		
	Bush		11G3195	1		
	Washer		12H2178	1		
M - 7	Lever - Handbrake - Complete		BHH538	1		
N - 8	Plug - Wing Light		BHA5145	2		
	Plug - Cigar Lighter		BHA4916	1		
	Plug - Rocker Switch Aperture - Heated Backlight		BHH533	1		
	Plug - Rocker Switch Aperture - Fog Lamp Switch		BHH533	1		
	Switch - Lighting		BHA5111	1		
	Switch - Wiper		BHA5110	1		
	Switch - Heater		BHA5113	1		
N - 18	Light - Courtesy	41	AVB494	1		
	Screw - Courtesy Light to Console	42	PMZ208	2		
	Washer - Spring - Courtesy Light to Console	43	LWZ202	2		
	Nut - Courtesy Light to Console	44	ANZ102	2		
	Lamp - Reverse		BHA5167	2		
	Lens		37H7512	1		
	Gasket		54578371	1	From ▲ To ▲	
	Bulb		270	1		

NOTE This PARTS AMENDMENTS ADVICE is issued to enable your Parts Lists to be maintained in an updated condition at all times. Once these amendments have been entered this advice sheet can be filed in the front of the Parts List Binder.

PARTS AMENDMENT ADVICE

Model	MG.B - BODY	PUB 1030	PA No. 76	Page 8	Date AUG 1972

Page No.	Description	Item Ill. no.	NEW Part Number	Qty.	Change Point	Remarks
N 23	Harness - Main - Rework		AYH9821	1		
	Harness - Main		BHH644	1		
R2 A	Shell Assembly - Body - Less Doors		HZA4057	1		
R 3	End Assembly - Front	1C	HZA4051	1		
RE 2	Door - RH	1	HZA4096	1		
	LH	2	HZA4097	1		
RL 2	Panel - Fascia		HZA4072	1		
	Tube - Bulkhead to Face Level Vent		BHH609	1		
	Vent - Face Level - RH		BHH501	1		
	- LH		BHH502	1		
RL 3	Console - Radio	13A	BHH473	1		
RM5 A	Cover - Gearbox and Tunnel		XGN2073	1		
	Carpet - Rear Compartment Assembly		XGN2072	1	YHN9 1774	
	Carpet - Rear Wheelarch - RH		XGN2062	1		
	- LH		XGN2063	1		
	Console - Tunnel Assembly		HYB4902	1		
	- Manual		BHH467	1		
	- Automatic		BHH468	1		
	Tray - Ash - Console Tunnel		BHH490	1		
	Arm Rest Assembly - Hinged		BHH689	1		
	Carpet - Toeboard - LH		X002079	1		
	Carpet - Pedal Box - LH		XGN2204	1		
	Carpet - Heelboard Assembly		XGN206T	1		

NOTE This PARTS AMENDMENTS ADVICE is issued to enable your Parts Lists to be maintained in an updated condition at all times. Once these amendments have been entered this advice sheet can be filed in the front of the Parts List Binder.

INFORMATION SHOWN HERE IS AN ADVANCE OF REPRINTED MATERIAL DUE FOR PUBLICATION.

Model M.G.B. MECHANICAL Parts List No. PUB1028 P.A. No. 75 Date JUNE, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
N - 18	23	LAMP ASSEMBLY - REVERSE		BHA5167	1	▲	Addition at change point unknown.

P.D 15

INFORMATION SHOWN HERE IS AN ADVANCE C[illegible]PRINTED MATERIAL DUE FOR PU[illegible]CATION.

Model M.G.B. / MECHANICAL Parts List No. PUB1028 P.A. No. 72 Date APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
AB - 3	27	Screw - Set - Main Bearing - Crankshaft		12B2356	10	▲	Addition at change point.
AB - 4	27	Piston Assembly		12H3584	4		
AB - 6	1A	Rod Assembly - Connecting		12H3596	4		
	2A	Bolt		32H514	8		
	6A	Bush - 1st Motion Shaft		22H1416	1		
	9A	Washer - Thrust - Upper		12H4212	2		
	9B	- Lower		12H4213	2		
	11A	Gear - Crankshaft		1A2028	1		
	14A	Dowel - Flywheel to Crankshaft		12H1301	1		
	15A	Pulley - Crankshaft		12H3515	1		
	18	Plate - Blanking - Petrol Pump Facing		2A265	1		
	19	Washer - Joint - Petrol Pump		2A113	1		
	20	Screw - Set		HZS504	2		Introduction of 1972 Face-Lift
	21	Washer - Spring		LWZ205	2		
		Nut		13H5872	8		
		Bearing - Connecting Rod - Half		8G2574	8		
AB - 7	27A	Gear - Camshaft		11G203	1		
	39A	Tappet		AEG584	8		
	40A	Rod - Push		12H3357	8		
AB - 8	1A	Head - Cylinder - Complete		12H2708	1		
	4A	Guide - Valve - Inlet		11G313A	4		
	5A	- Exhaust		12B1339	4		
	9A	Stud - Water Outlet		CLS2515	3		

P.D 15

* ▲ Change point unknown

INFORMATION SHOWN HERE IS AN ADVANCE OF REPRINTED MATERIAL DUE FOR PUBLICATION.

Model M.G.B./ MECHANICAL Parts List No. PUB1028 P.A. No. 72 Date - APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
AB - 8	25A	Stud - Manifold to Cylinder Head		FLS2513	6		
AB - 9	12A	Spring - Valve		12H3352	8		
	14A	Spring - Valve - Collar		12H3354	8		
	19A	Valve - Inlet		AYH574	4		
	20A	- Exhaust		AYH575	4		
	21A	Spring - Valve - Cap		12H3353	8		
AB - 10	4A	Plug - Valve Rocker Shaft		6K878	1		
	20A	Shim - Valve Rocker Shaft Bracket		12H3960	2		
	34A	Gasket - Cylinder Head		GEG366	1		
	39	Bracket - Engine Sling		12A1968	2	▲	Addition at change point
AB - 11	1A	Cover Assembly - Front		12H3510	1		Introduction of 1972 Face-Lift.
	2A	Seal - Oil		13H6516	1		
	13A	Cover - Side Cylinder		12H3926	1		
	43	Gasket		12H1139	1		
	44	Bolt — Side Cover to Crankcase		HBZ520	1		
	45	Bush — Side Cover to Crankcase		12A1176	1		
	46	Washer - Cup — Side Cover to Crankcase		AYA258	1		
AB - 12	44A	Washer - Spring		LWZ306	8		
AB - 13	1A	Pump Assembly - Oil		12H1429	1		
	31B	Tube - Oil Dipper Rod		12H3351	1		
	34A	Rod - Oil Dipper		12H3963	1		
AB - 14	2A	Oil Filter Head - Complete		12H3998	1		
	2B	Valve - Relief		12H6950	1		

P.D 15

* ▲ Change point unknown.

INFORMATION SHOWN HERE IS AN ADVANCE OF REPRINTED MATERIAL DUE FOR PUBLICATION.

Model M.G.B. / MECHANICAL Parts List No. PUB1028 P.A. No. 72 Date APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
AB - 14	4A	Element - Oil Filter		GFE139	1		
AB - 15	2A	Pump - Water		GWP117	1		
	5A	Bearing Assembly		12A1389	1		
	9A	Hub		12H3362	1		
	10A	Seal		13H6187	1		
	11A	Pulley - Fan and Water Pump		12H3696	1		
AB - 16	30A	Washer		PWZ204	4		
	32A	Screw		HZS415	4		
	37	Spacer For Fan		12H3910	1		
	38	Bolt - Fan to Water Pump Pulley Hub		HBZ413	4		
AB - 19	3B	Manifold - Inlet		8G774	1	▲	Addition at change point.
	33A	Nut for Stud		12A1975	6		Introduction of 1972 Face-Lift.
AC - 2	40A	Bracket - Engine Mounting - RH		AHH7890	1		
	40B	- LH		BHH640	1		
AC - 3	19A	Cable Assembly - Choke Control		BHH651	1		
		Washer - Plain - Pin to Throttle Lever		PWZ103	1		
AC - 4		Bracket - Choke Cable		12H3916	1		
		Pin] Choke Cable to Inner Relay		AHA6367	1		
		Screw] Shaft Bracket		53K3503	1		
		Lever Assembly - Throttle		BHH632	1		
		Lever - Pick-Up		AUE578	1		
		Lever - Pick-Up		AUE586	1		
		Lever Assembly - Choke		BHH636	1		

P.D15

* ▲ Change point unknown.

INFORMATION SHOWN HERE IS AN ADVANCE OF REPRINTED MATERIAL DUE FOR PUBLICATION.

Model M.G.B. / MECHANICAL Parts List No. PUB1028 P.A. No. 72 Date APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
AC - 4		Trunnion Bracket - Choke and Throttle Cables		BHH558	1		
		Screw - Trunnion Bracket to Manifold		HZS505	1		
		Washer - Spring - Trunnion Bracket to Manifold		LWZ205	1		
		Screw - Trunnion Bracket to Heatshield		HZS404	1		
		Washer - Spring - Trunnion Bracket to Heatshield		LWZ204	1		
		Nut		FNZ504	1		
		Washer - Plain		PWZ204	1		
		Screw - Choke Cable to Trunnion Bracket		ACA5453	1	▲	Addition at change point
D - 2	37	Petrol Filler - Micro		BHA4952	1		Introduction of 1972 Face-Lift.
D - 3		Clip - Front Main Feed Pipe to LH Valance		PCR507	2		
		Screw Clip to Valance Bracket		PMZ308	2		
		Washer - Spring		LWZ203	2		
		- Plain		PMZ203	2		
		Hose - Flexible - Filter to Front Carburettor		BHH641	1		
		Pipe - Petrol - Main Feed to Filter - Bent		BHH135	1		
		Hose - Flexible - Main Feed to Filter		BRT2804	1		
		Clip - Flexible Hose to Filter and Carburettor		ACH5854A	4		
		- Flexible Hose to Valance Bracket		PCR1007	1		
		Screw - Clip to Valance Bracket		PMZ308	1		
		Washer - Spring		LWZ203	1		

P.D 15

▲ Change point unknown.

INFORMATION SHOWN HERE IS AN ADVANCE OF REPRINTED MATERIAL DUE FOR PUBLICATION.

Model M.G.B. / MECHANICAL Parts List No. PUB1028 P.A. No. 72 Date APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
D - 3		Plain Washer		PNZ103	1		
		Pipe - Overflow - Front Carburettor		BHH669	1		
		- Rear Carburettor		BHA670	1		
		Pipe - Flexible - Carburettor to Carb.		BRT2409	1		
D - 4	50	Piece - Distance		1B2925	1		
	51	Rod - Control		12H2612	1		
	52	Joint - Ball		AHB9898	2		
		Nut		FNZ503	2		
D - 8	1A	Shield - Heat		12H3948	1		
	1B	Washer		2K6810	1		
	6A	Cleaner - Air - Front		BHH546	1		
	7A	- Rear		BHH547	1		
	22A	Assembly - Choke Cable Abutment		BHH564	1		
	23	Washer - Plain		PWZ103	1		
	24	Spring - Return - Choke		AEC2075	1	▲	Addition at change point
	25	Washer, Plug — Adaptor Manifold - Anti Run -on Valve		51K3811	1		Introduction of 1972 Face-Lift.
	26			AHH8414	1		
D - 9	1C	Lever Assembly - RH		AUE587	1		
	1D	- LH		AUE586	1		
	12	Carburettor Assembly - Front		CUD9115	1		
	13	- Rear		CUD9116	1		
	14	Gasket - Carburettor to Inlet Manifold		AEC2083	6		
		Nut		FNZ505	4		

P.D15

▲ Change point unknown.

INFORMATION SHOWN HERE IS AN ADVANCE OF REPRINTED MATERIAL DUE FOR PUBLICATION.

Model M.G.B. / MECHANICAL Parts List No. PUB1028 P.A. No. 72 Date APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
D - 9		Washer - Plain		PWZ105	2	▲	Addition at change point.
D - 11	61	Seal - Mixture Screw		AYH2882	1	YHN9/1691 YHN10/569	
D - 13	61	Seal - Mixture Screw		AYH2882	1		
E - 2	9A	Cover Assembly - Clutch		13H6350	1		
	10A	Plate - Clutch		13H6351	1		
	13A	Bearing Assembly		13H5980	1		
	14A	Retainer - Bearing		75020	2		
F - 7	30	Bracket - Wiring Clip - Complete - Top RH Bolt on Front Gearbox Case		22B512	1		
	31	Bracket - Wiring Clip - Complete - Top Starter Motor Bolt		22H1303	1		
	32	Clip - Bracket - Top - RH Rear of Gearbox		ACH579	1		
F - 12	33	Washer - Plain		PWZ105	1	▲	
F - 21	28	Screw - Set - Long (Remote Control Housing to Extension)		HCZ518	4		
	29	- Short (Remote Control Housing to Extension)		ZCS508	2		
	30	Washer - Spring (Rear Extension to Gearbox)		LWZ305	6		
	31	Gasket (Rear Extension to Gearbox)		22B371	1		
	32	Washer - Spring (Rear Extension to Gearbox)		LWZ305	8		
F - 22	34	Wheel - Reverse		22H309	1		
	35	Bush		22H310	1		
		Shaft - 3rd Motion		22B424	1		
F - 24	37A	Plug		22B612	1		

P.D 15

* ▲ Change point unknown

INFORMATION SHOWN HERE IS AN ADVANCE OF REPRINTED MATERIAL DUE FOR PUBLICATION.

Model M.G.B. / MECHANICAL Parts List No. PUB1028 P.A. No. 72 Date - APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
F - 24	39	Plunger - Detent - Reverse		22B614	1		
F - 25	40	Lever - Clutch Withdrawal		22H1057	1		
	41	Bush		11G3195	1		
	42	Washer		12H2178	1		
F - 28	51	Bracket - Wiring Clip - Complete - Top RH Bolt on Front Gearbox Case		22B512	1		
	52	- Wiring Clip - Complete - Top Starter Motor Bolt		22H1303	1		
	53	Washer - Plain		PWZ105	1		
F - 30-1	39	Cap - Slave - For Prop Shaft Bolt		22B626	4		
F - 33	22	Handle (Oil Dipper Rod)		AHC385	1		
	23	Shaft - Flexible (Oil Dipper Rod)		AHC386	1		
	24	Blade (Oil Dipper Rod)		AHC387	1		
	1A	Pinion - Speedometer		22B654	1	▲	Addition at change point.
M - 7	1A	Lever - Handbrake - Complete		BHH538	1		Introduction of 1972 Face-Lift.
	4A	Rod - Pawl		BHH548	1		
N - 18	40	Courtesy Light		AVB494	1		
	41	Screw (Courtesy Light to Console)		PMZ208	2		
	42	Washer - Spring (Courtesy Light to Console)		LWZ202	2		
	43	Nut (Courtesy Light to Console)		ANZ102	2		
N - 23		Main Harness - Rework		AYH9281	1		
		Main Harness		BHH644	1		
N - 26	37	Bracket - Clip to Front Gearbox Case		22B512	1		
	41	- Clip to RH Rear Gearbox		AHC579	1		

P.D 15

▲ Change point unknown

INFORMATION SHOWN HERE IS AN ADVANCE OF REPRINTED MATERIAL DUE FOR PUBLICATION.

Model M.G.B. / MECHANICAL **Parts List No.** PUB1028 **P.A. No.** 72 **Date** APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
N - 26	45	Bracket - Clip to Starter Motor		22H1303	1		
	46	Washer - Plain		PWZ105	1		
N - 28	1B	Plug - Rocker Switch Aperture - Fog Lamp Switch		BHH533	1		
	4A	Switch - Lighting		BHA5111	1	BHA 5111.	
	7A	- Wiper		BHA5110	1	BHA 5110 ▲	Addition at change point
	12A	Plug - Rocker Switch Aperture - Heated Backlight		BHH533	1		Introduction of 1972 Face-Lift
	26A	- Snap-In Wing Light		BHA5145	2		
	29	- Cigar Light		BHA4919	1		
		Switch - Heater		BHA5113	1		

P.D15

* ▲ Change point Unknown

Model M.G.B. / BODY Parts List No. PUB1030 P.A. No. 72 Date APRIL, 1972.

PAGE	ITEM	DESCRIPTION	PART NO.	NEW PART NO.	QTY.	CHANGE POINT	REMARKS
R2 - A		Body Shell - Less Doors		HZA4057	1		
R - 3	1C	End Assembly - Front		HZA4051	1	▲	Addition at change point.
RE - 2	1	Door - RH		HZA4096	1		
	2	- LH		HZA4097	1		
RG - 2		Sun Visor Assembly	BHH649	BHH269	1		Correction.
RL - 2	1A	Panel - Fascia		HZA4072	1		
	39	Tube - Bulkhead to Face Level Vent		BHH609	2		
	40	Face Level Vent - RH		BHH501	1	▲	Addition at change point.
	41	- LH		BHH502	1		Introduction of 1972 Face-Lift.
RL - 3	13A	Console - Radio		BHH473	1		

* ▲ Change point unknown