



Narrow gearbox tunnel on YGHN3/5166 (note the hump below the gear lever and the overall narrowness of the tunnel)



1968 Wide tunnel on a YGHN4 (note that the hump has gone and the tunnel is flatter and wider)